

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/10/2025

Submitted Date:

04/16/2025

Document Number:

719000019

FIELD INSPECTION FORM

Loc ID: 326281 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 17 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kosola, Jason		jason.kosola@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Huntington, Heather		hhuntington@enduringresources.com	SJB inspections
Walter, Klye		kwalter@enduringresources.com	SJB inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216163	WELL	PR	03/13/2001	CBM	067-07769	BURNETT 2-1	PR
480579	SPILL OR RELEASE	CL	12/01/2021		-	BURNETT 2-1	CL

General Comment:

Inspection Report Summary
On 4-10-25 I Inspector Charles Garcia conducted an on-site inspection.
Location: Burnett 2-1
Operator: Enduring resources
API#: 067-07769
County: LaPlata
Separator and partially buried vessel have been removed since last compliance inspection. No Form 42 notice of major change or Form 27s in well file. See Equipment and Tank sections for corrective actions.
Date

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Location sign at entrance		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	1-800-916-7897		Date: _____
Corrective Action:			
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Chainlink aroud location		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Cattle panels		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Flow Line	# 3		
Comment:	2 flowlines sticking out of ground by meter house not labled OOSLT see picture #10		
Corrective Action:	Lock out and tag out caped flowlines per rule 11.02 OSLT		Date: <u>04/23/2025</u>
Type: Other	# 1		
Comment:	wellhead		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Meter house calibration card is up to date see pictures #7 #8		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:	One dead man marker laying down see picture #4		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		

Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 3		
Comment:	Electric Panels see Picture #9		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 0		
Comment:	Separator has been removed since last compliance inspection. No notice of major change or Form 27 in well file		
Corrective Action:	Submit Form 27 and follow up with SW EPS Jason Kosola about sampling requirements		Date: 07/10/2025
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	OTHER	STEEL AST		37.234544,-107.818613
Comment:	95 bbl partially buried vessel at 37.234544,-107.818613 has been removed, no notice of major change or form 27 in well file				
Corrective Action:	File Form 27 and follow up with SW EPS Jason Kosola about required sampling				Date: 06/10/2025

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities

Facility ID: 216163 Type: WELL API Number: 067-07769 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 01/30/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 480579 Type: SPILL OR API Number: - Status: CL Insp. Status: CL

Producing Well

Comment:		
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Date: 06/10/2025

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Check Dams	Pass					
Gravel	Pass					
Waddles	Fail					

Comment: [Waddles filled with sediment refer to picture #5](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000022	Locatin Pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7007166