

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2025

Submitted Date:

04/16/2025

Document Number:

719000020

**FIELD INSPECTION FORM**Loc ID 326613 Inspector Name: GARCIA, CHARLES On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10663

Name of Operator: ENDURING RESOURCES LLC

Address: 6300 S SYRACUSE WAY, SUITE 525

City: CENTENNIAL State: CO Zip: 80111

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

16 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Kosola, Jason		jason.kosola@state.co.us	
Walter, Klye		kwalter@enduringresources.com	SJB inspections
Huntington, Heather		hhuntington@enduringresources.com	SJB inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258994	WELL	PR	01/17/2001	CBM	067-08398	CRADER 2-3	PR

**General Comment:**

Inspection Report Summary

On 4-10-25 I Inspector Charles Garcia  
conducted an on-site inspection.

Location: CRADER 2-3

Operator: Enduring resources

API#: 067-08398

County: LaPlata

Separator and partially buried vessel have been removed since last compliance inspection. No Form 42 notice of major change or Form 27s in well file. See Equipment and Tank sections for corrective actions

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Gravel compacted			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	OTHER			
Comment:	Sign at entrance of location			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	1-800-916-9897			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	DEBRIS			
Comment:	Dried weed debris noted inside fence corners and perimeter of location outside fencing see pictures #5 #6			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PUMP JACK			
Comment:	Cattle panels			
Corrective Action:				Date:
Type	LOCATION			
Comment:	6' chain link fencing with visual barrier and topped with barb wire.			
Corrective Action:				Date:
<b>Equipment:</b>				
				corrective date
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:				Date:
Type: Flow Line	# 1			
Comment:				
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Wellhead			

Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Meter house calibration card up to date see pictures #3 #4		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 0		
Comment:	Separator has been removed since last compliance inspection. No notice of major change or Form 27 in well file.		
Corrective Action:	Submit Form 27 and follow up with SW EPS Jason Kosola about sampling requirements	Date:	07/10/2025
Type: Ancillary equipment	# 1		
Comment:	Meter house calibration card up to date		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment. Electrical control panel		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	OTHER	STEEL AST		
Comment:	95 bbl partially buried vessel at has been removed, no notice of major change or form 27 in well file				
Corrective Action:	File Form 27 and follow up with SW EPS Jason Kosola about required sampling				Date: 07/10/2025

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	258994	Type:	WELL	API Number:	067-08398	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	01/30/2025		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000023	Inspection photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7007167">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7007167</a>