

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2025

Submitted Date:

04/16/2025

Document Number:

719000021

FIELD INSPECTION FORMLoc ID 326276 Inspector Name: GARCIA, CHARLES On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10663

Name of Operator: ENDURING RESOURCES LLC

Address: 6300 S SYRACUSE WAY, SUITE 525

City: CENTENNIAL State: CO Zip: 80111

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kosola, Jason		jason.kosola@state.co.us	
Huntington, Heather		hhuntington@enduringresources.com	SJB inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Walter, Klye		kwalter@enduringresources.com	SJB inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216153	WELL	PR	02/04/2000	CBM	067-07759	CRADER 3-2	PR

General Comment:

Inspection Report Summary
 On 4-10-25 I Inspector Charles Garcia conducted an on-site inspection.
 Location: CRADER 3-2
 Operator: Enduring resources
 API#: 067-07759
 County: LaPlata
 Separator and partially buried vessel have been removed since last compliance inspection. No Form 42 notice of major change or Form 27s in well file. See Equipment and Tank sections for corrective actions.
 Referred storm water issues to Steve Labowski

Location**Lease Road:**

Type	Access		
comment:	Gravel compacted		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Sign at entrance of location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	1-800-916-7897	Date:	
Corrective Action:			

Good Housekeeping:

Type	DEBRIS		
Comment:	Tumble weeds gathering along fence line around location see pictures #5 #6		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	4ft Barbwire around location H brace on west of location falling over See Picture #10		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Progressive Cavity	# 1		
Comment:	DYNA pump		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Hydraulic		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Electric panel		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Vertical Separator	# 0		
Comment:	Separator has been removed since last compliance inspection. No notice of major change or Form 27 in well file.		
Corrective Action:	Submit Form 27 and follow up with SW EPS Jason Kosola about sampling requirements	Date:	07/10/2025
Type: Other	# 1		
Comment:	Meter house meter calibrated on 2-5-25		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	OTHER	STEEL AST		37.232306,-107.838824
Comment:	95 bbl partially buried vessel at 37.232306,-107.838824 has been removed, no notice of major change or form 27 in well file				
Corrective Action:	File Form 27 and follow up with SW EPS Jason Kosola about required sampling				Date: 07/10/2025

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities										
Facility ID:	216153	Type:	WELL	API Number:	067-07759	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:										
Corrective Action:									Date:	
BradenHead										
Date of Last Brhd Test:	01/30/2025		Annual Brhd Completed?	Yes						
Last Brhd Test Results	Initial Surf Csg Pressure:	0		Fluid Type:						
	End Surf Csg Pressure:	0								
Comment:										
Corrective Action:									Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000024	Location Pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7007168