

**Operator: BONANZA CREEK ENERGY OPERATING CO.**

**Location Name: Pronghorn T-3 Pad**

**Loc ID: 431184**

**Inspection: 718700173**




**Exhibit A**



**Exhibit B**



**Exhibit C**



**Exhibit D**



**Exhibit E**

**CA:** Hydrocarbon staining observed throughout the location. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).D.

**CA Resolution:** Operator has address the reported issue in order to comply with Rule 1002.f.(2).D.

**CA:** This location does not comply with Rule 1003. During this inspection, it was observed that interim areas do not appear to be progressing towards reclamation standards with evidence of non-uniform vegetation cover resulting in bare/unstabilized soils and evidence of undesirable vegetation (e.g. russian thistle). Additional reclamation activities are required. Refer to attached inspection photos. Comply with Rule 1003. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

**CA Resolution:** Operator has applied hydromulch and reseeded in order to comply with Rule 1004.