

Inspection Photos

API: 011-05057

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 4/10/2025

County: Prowers



Inspection Photos



Photo 1. Drone photo (taken on 5/8/24) facing down toward the wellsite. There is an area with no vegetation which appears impacted soil from a historical spill.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 011-05057 | Date: 4/10/2025

Inspection Photos



Photo 2. Drone photo (taken on 2/4/25) facing down toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 011-05057 | Date: 4/10/2025

Inspection Photos




Photo 3. Facing northeast toward the wellsite. The concrete has been removed and the location is seeded and straw mulched. Some of the mulch has blown off.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 011-05057 | Date: 4/10/2025

Inspection Photos




Photo 4. Facing toward the wellhead.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 011-05057 | Date: 4/10/2025

Inspection Photos



Photo 5. Facing south at the location. This is the area of suspected impacts from the well. See photo #1.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 6. Facing north at the location. There are two wood railroad ties and a partial shed that remain.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources