

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Dry Hollow Interconnect

Location ID: 479290



Photo # 2310 From entrance to location



Photo # 2311 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Dry Hollow Interconnect

Location ID: 479290



Photo # 2312 Location



Photo # 2313 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Dry Hollow Interconnect

Location ID: 479290



Photo # 2314 Location



Photo # 2315 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Dry Hollow Interconnect

Location ID: 479290



Photo # 2316 Location



Photo # 2317 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Dry Hollow Interconnect

Location ID: 479290



Photo # 2318 Location



Photo # 2319 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Dry Hollow Interconnect

Location ID: 479290



Photo # 2320 Open ended load line



Photo # 2321 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Dry Hollow Interconnect

Location ID: 479290



Photo # 2322 Location #, legal location & latitude/longitude on sign are incorrect/not in compliance with CECMC rules