

# Interim Reclamation and Stormwater Inspection

Date: 04/11/2025

Operator: WESTERN OPERATING COMPANY - 95620

Location ID: 312292

Inspection Document #: 718700296

Logan County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Propst 2  
Location ID: 312292




**Photos 1 & 2.** South of former heater treater. Additional reclamation activities are required to stabilize areas experiencing bare soil and/or non-uniform vegetation cover

Inspection Photos  
Location Name: Propst 2  
Location ID: 312292



**Photos 3 & 4.** Eastern side of pit. Additional reclamation activities are required to stabilize areas experiencing bare soil and/or non-uniform vegetation cover.

Inspection Photos  
Location Name: Propst 2  
Location ID: 312292



**Photos 5 & 6.** Southern extent of the eastern salt kill excavation (Photo 5; left) and western side of eastern salt kill area excavation (Photo 6; right). Additional reclamation activities are required to stabilize areas experiencing bare soil and/or non-uniform vegetation cover.

Inspection Photos  
Location Name: Propst 2  
Location ID: 312292



**Photo 7.** Southern extent of the western salt kill excavation. Additional reclamation activities are required to stabilize areas experiencing bare soil and/or non-uniform vegetation cover.

Inspection Photos  
Location Name: Propst 2  
Location ID: 312292



**Photos 8 & 9.** Southern portion of the western excavation/stockpile. Evidence of sediment discharge into the adjacent lands. Stormwater control measures do not appear to be adequate around the perimeter of the excavation.

Inspection Photos  
Location Name: Propst 2  
Location ID: 312292



**Photos 10 & 11.** Taken from the northwestern portion of the salt kill excavation. It appears that stormwater runoff from the excavated salt kill area is being channeled through a livestock trail and causing erosion degradation (Photo 11; right). Stormwater control measures do not appear to be adequate around the perimeter of the excavation.

Inspection Photos  
Location Name: Propst 2  
Location ID: 312292



**Photos 12 & 13.** Taken near the northern portion of the salk kill excavation. Silt fence does not appear to be properly maintained.

Inspection Photos  
Location Name: Propst 2  
Location ID: 312292



**Photos 14 & 15.** Northeastern corner of pit. Additional reclamation activities are required to stabilize areas experiencing bare soil and/or non-uniform vegetation cover.

Inspection Photos  
Location Name: Propst 2  
Location ID: 312292



Photos 16 & 17. Overview of pit/salt kill excavation.