

Interim Reclamation and Stormwater Inspection

Date: 04/11/2025

Operator: WESTERN OPERATING COMPANY - 95620

Location ID: 312228

Inspection Document #: 718700298

Logan County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Propst C-1X
Location ID: 312228



Photo 1. Northeastern guyline anchor maker needs to be reinstalled.

Inspection Photos
Location Name: Propst C-1X
Location ID: 312228



Photos 2 & 3. Erosion degradation evident on the southeastern portion of the production areas. No apparent stormwater control measures/BMPs observed at the time of this inspection.

Inspection Photos
Location Name: Propst C-1X
Location ID: 312228



Photo 4. Pipe (debris) remains from the previous inspection; south of the well location in nearby drainage.

Inspection Photos
Location Name: Propst C-1X
Location ID: 312228



Photos 5 & 6. Erosion degradation evident on the southwestern portion of the production areas. No apparent stormwater control measures/BMPs observed at the time of this inspection.