

Inspection Photos
Location Name: Lincoln 2 (OWP)
API: 05-061-06008



Wellhead is fenced with wire panels



Northwest corner of the tank battery looking southeast

Inspection Photos
Location Name: Lincoln 2 (OWP)
API: 05-061-06008



Southwest corner of the tank battery looking northeast




Southeast corner of the tank battery looking northwest

Inspection Photos
Location Name: Lincoln 2 (OWP)
API: 05-061-06008



These are all pictures of inside the metal shed associated with the injection well. There is an Arrow gas engine along with a triplex pump and dump valves.

Inspection Photos
Location Name: Lincoln 2 (OWP)
API: 05-061-06008



Inside the metal shed