

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2025

Submitted Date:

04/18/2025

Document Number:

715202100

FIELD INSPECTION FORM

Loc ID 324794 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 16520
Name of Operator: CHEMCO INC
Address: 6970 SOUTH HOLLY CIR STE 206
City: CENTENNIAL State: CO Zip: 80112

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beasley, Nolan		nolan.beasley@state.co.us	
Quint, Craig		craig.quint@state.co.us	
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212648	WELL	IJ	02/06/2023	DSPW	061-06008	LINCOLN 2 (OWP)	IJ

General Comment:

SE Compliance Specialist Brian Welsh conducted a Routine UIC Inspection
Well is in the OWP per order #1V-838 (Inability to pay)

Location

Lease Road:			
Type	Access		
comment:	Two track through pasture		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Lease signs by tanks		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Wire panels around wellhead		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Wire panels around tank battery		
Corrective Action:			Date:

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Arrow gas engine in metal shed		
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Gas scrubber and triplex pump in metal shed, chemical tank next to metal shed		
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	FIBERGLASS AST		38.415630,-102.441750

Comment:		
Corrective Action:		Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 212648 Type: WELL API Number: 061-06008 Status: IJ Insp. Status: IJ

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg <u>3 PSIG</u> (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg <u>0 PSIG</u>	Previous Test Pressure _____	Inj Zone: <u>MSSP</u>
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: <u>05/04/2021</u>
			AnnMTReq: <u>NO</u>

Comment: CASING HAD STRONG BLOW, DIED WITHIN A MINUTE. TBG IJ @ 3 PSIG.
PASSING MIT PERFORMED ON 5/4/21

Corrective Action: _____ Date: _____

Method of Injection: GRAVITY FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment:

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715202195	location and equipment photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7012028