

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2025

Submitted Date:

04/12/2025

Document Number:

708906237**FIELD INSPECTION FORM**Loc ID 324013 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:21 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211490	WELL	PR	09/01/2004	GW	045-07250	GIBSON GULCH UNIT 10-30 D	PR

General Comment:**CECMC Inspection/Audit Report Summary**

On 04/10/2025 at approximately 13:55 hours, I, Compliance Specialist, Wayne Smelser
Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 10-30 D Pad.
Location # 324013 in Garfield County Colorado.
Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area.
While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Housekeeping - Unused equipment on location with a CA date of 05/12/2025
2. Equipment - Unused flowline lacks lockout tagout (OOSLAT) with a CA date of 04/19/2025
3. Equipment - PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules with a CA date of 04/19/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection/audit report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Production tank is disconnected & not in use/unused equipment Additionally there's staining on top of the tank & down the side of tank that indicates the tank may lack integrity.		
Corrective Action:	The storage or placement of equipment and supplies not necessary for use on location is prohibited.	Date:	05/12/2025

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Pig station - pipe rail fence		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panels		

Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Wildlife fencing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bradenhead	# 1		
Comment:	Taylor plug located on bradenhead, bradenhead valve is accessible.		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	PRV & rupture disc vent lines on separator do not comply with CECMC pressure safety device rules		
Corrective Action:	Comply with CECMC pressure safety device rules	Date:	04/19/2025
Type: Pig Station	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Unused flowline lacks lockout tagout (OOSLAT)		
Corrective Action:	Comply with CECMC 600 & 1100 series rules	Date:	04/19/2025
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	STEEL AST		,	

Comment:	Production tank is disconnected & not in use/unused equipment - please refer to Housekeeping for CA Additionally there's staining on top of the tank & down the side of tank that indicates the tank may lack integrity.	
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211490	Type:	WELL	API Number:	045-07250	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other						Erosion developing on west side of location
		Compaction				Light compaction in some sections
Compaction						
		Ditches				
		Culverts				
Gravel						Sparse to none in most areas
		Gravel				Sparse to none

Comment: [Erosion starting to develop on western edge of location](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Housekeeping & Equipment for corrective actions	smelserw	04/12/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404162707	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7002366
708906238	Inspection/Audit 708906237 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7002364
708906239	Inspection/Audit 708906237 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7002365