

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC Jolley KP 22-21 Pad

Location ID: 335209



Photo # 2056 From entrance to location

Photo # 2057 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Jolley KP 22-21 Pad

Location ID: 335209



Photo # 2058 Location



Photo # 2059 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Jolley KP 22-21 Pad

Location ID: 335209



Photo # 2060 Location



Photo # 2061 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Jolley KP 22-21 Pad

Location ID: 335209



Apr 16, 2025 at 1:40:22 PM
CO



Apr 16, 2025 at 1:44:42 PM
CO

Photo # 2062 Location

Photo # 2063 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Jolley KP 22-21 Pad

Location ID: 335209



Photo # 2064 Open ended load line



Photo # 2065 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Jolley KP 22-21 Pad

Location ID: 335209



**Photo # 2066 Open ended kelly hose/wildlife hazard
/available for entry by wildlife**



**Photo # 2067 PRV vent line does not comply with CECMC
pressure safety device rules or general safety rules**

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Jolley KP 22-21 Pad

Location ID: 335209



Photo # 2068 Multiple wellhead signs weathered & illegible /not in compliance with CECMC rules



Photo # 2069 Wellhead sign weathered & illegible/not in compliance with CECMC rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Jolley KP 22-21 Pad

Location ID: 335209



Photo # 2070 Hole in secondary containment liner/liner needs maintenance



Photo # 2071 Hole in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Jolley KP 22-21 Pad

Location ID: 335209



Photo # 2072 Total of 6 production tanks on location however operators FORM 2A only lists 5/not in compliance with CECMC rules



Photo # 2073 Total of 6 production tanks on location however operators FORM 2A only lists 5/not in compliance with CECMC rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC Jolley KP 22-21 Pad

Location ID: 335209



Photo # 2074 Total of 9 separators on location however operators FORM 2A only lists 8/not in compliance with CECMC rules