

Arch Oil & Gas LLC
J P Weise 2
Location ID: 312744




Missing information




Unused equipment

Arch Oil & Gas LLC
J P Weise 2
Location ID: 312744



Label on opposite side of tank



Damaged label

Arch Oil & Gas LLC
J P Weise 2
Location ID: 312744



Stained soil below valve



Debris

Arch Oil & Gas LLC
J P Weise 2
Location ID: 312744



Debris



Debris

Arch Oil & Gas LLC
J P Weise 2
Location ID: 312744



Missing required information

Debris

Arch Oil & Gas LLC
J P Weise 2
Location ID: 312744



Debris



Missing required information

Arch Oil & Gas LLC
J P Weise 2
Location ID: 312744



Debris



Debris

Arch Oil & Gas LLC
J P Weise 2
Location ID: 312744



Debris. Stained soil.



Leaking equipment with stained soil

Arch Oil & Gas LLC
J P Weise 2
Location ID: 312744



Debris



Debris

Arch Oil & Gas LLC
J P Weise 2
Location ID: 312744



Debris



Debris

Arch Oil & Gas LLC
J P Weise 2
Location ID: 312744



Unmarked anchor



Location from Southeast entrance

**Arch Oil & Gas LLC
J P Weise 2
Location ID: 312744**



Location from North corner



Location from South corner