

**Inspection/Audit Photos**  
**Location Name: QB Energy SCHWARTZ (O2E) Pad**  
**Location #: 334740**



**Photo # 3546 From entrance to location**



**Photo # 3547 From entrance to location**

Inspection/Audit Photos  
Location Name: QB Energy SCHWARTZ (O2E) Pad  
Location #: 334740




Photo # 3548 Location

Photo # 3549 Location

**Inspection/Audit Photos**  
**Location Name: QB Energy SCHWARTZ (O2E) Pad**  
**Location #: 334740**



**Photo # 3550 Location**

**Photo # 3551 Location**

**Inspection/Audit Photos**  
**Location Name: QB Energy SCHWARTZ (O2E) Pad**  
**Location #: 334740**



**Photo # 3552 Location**



**Photo # 3553 Location**

**Inspection/Audit Photos**  
**Location Name: QB Energy SCHWARTZ (O2E) Pad**  
**Location #: 334740**



**Photo # 3554 Location**



**Photo # 3555 Location**

**Inspection/Audit Photos**  
**Location Name: QB Energy SCHWARTZ (O2E) Pad**  
**Location #: 334740**



**Photo # 3556 Location**



**Photo # 3557 Location**

**Inspection/Audit Photos**  
**Location Name: QB Energy SCHWARTZ (O2E) Pad**  
**Location #: 334740**



**Photo # 3558 Excavated area around SCHWARTZ 2-14A (O2E)**

**Photo # 3559 Excavated area around SCHWARTZ 2-14A (O2E)**

**Inspection/Audit Photos**  
**Location Name: QB Energy SCHWARTZ (O2E) Pad**  
**Location #: 334740**



**Photo # 3560 Excavated area around SCHWARTZ 11-2A (O2E)**

**Photo # 3561 Excavated area around SCHWARTZ 11-2A (O2E)**

Inspection/Audit Photos  
Location Name: QB Energy SCHWARTZ (O2E) Pad  
Location #: 334740



Photo # 3562 Excavated areas in front of separators lack wildlife egress/wildlife hazard

Photo # 3563 Excavated area in front of separators not fully enclosed by cattle panels/wildlife hazard & personnel hazard

**Inspection/Audit Photos**  
**Location Name: QB Energy SCHWARTZ (O2E) Pad**  
**Location #: 334740**



**Photo # 3564 Excavated area in front of separators not fully enclosed by cattle panels/wildlife hazard & personnel hazard**



**Photo # 3565 Gate for panels around wellhead excavation areas open/wildlife hazard/available for entry by wildlife**

**Inspection/Audit Photos**  
**Location Name: QB Energy SCHWARTZ (O2E) Pad**  
**Location #: 334740**



**Photo # 3566 Excavated area around wellhead lacks wildlife egress/wildlife hazard**

**Photo # 3567 Excavated area around wellhead lacks wildlife egress/wildlife hazard**

**Inspection/Audit Photos**  
**Location Name: QB Energy SCHWARTZ (O2E) Pad**  
**Location #: 334740**



**Photo # 3568 Poly pipe open ended/wildlife hazard  
/available for entry by wildlife**



**Photo # 3569 Poly pipe open ended/wildlife hazard  
/available for entry by wildlife**

**Inspection/Audit Photos**  
**Location Name: QB Energy SCHWARTZ (O2E) Pad**  
**Location #: 334740**



**Photo # 3570 Unused equipment**

**Photo # 3571 Small amount of weeds in secondary containment**

**Inspection/Audit Photos**  
**Location Name: QB Energy SCHWARTZ (O2E) Pad**  
**Location #: 334740**



**Photo # 3572 Small amount of weeds in secondary containment**



**Photo # 3573 Small amount of weeds in secondary containment**

**Inspection/Audit Photos**  
**Location Name: QB Energy SCHWARTZ (O2E) Pad**  
**Location #: 334740**



**Photo # 3574 Debris**



**Photo # 3575 Debris**