

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2025

Submitted Date:

04/16/2025

Document Number:

719000019**FIELD INSPECTION FORM**Loc ID 326281 Inspector Name: GARCIA, CHARLES On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10663Name of Operator: ENDURING RESOURCES LLCAddress: 6300 S SYRACUSE WAY, SUITE 525City: CENTENNIAL State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Walter, Klye		kwalter@enduringresources.com	SJB inspections
Huntington, Heather		hhuntington@enduringresources.com	SJB inspections
Kosola, Jason		jason.kosola@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216163	WELL	PR	03/13/2001	CBM	067-07769	BURNETT 2-1	PR
480579	SPILL OR RELEASE	CL	12/01/2021		-	BURNETT 2-1	CL

General Comment:

Inspection Report Summary
 On 4-10-25 I Inspector Charles Garcia conducted an on-site inspection.
 Location: Burnett 2-1
 Operator: Enduring resources
 API#: 067-07769
 County: LaPlata
 Separator and partially buried vessel have been removed since last compliance inspection. No Form 42 notice of major change or Form 27s in well file. See Equipment and Tank sections for corrective actions.
 Date

LocationOverall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Location sign at entrance		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	1-800-916-7897		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Chainlink around location		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	wellhead		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 3		
Comment:	Electric Panels see Picture #9		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 0		

Comment:	Separator has been removed since last compliance inspection. No notice of major change or Form 27 in well file			
Corrective Action:	Submit Form 27 and follow up with SW EPS Jason Kosola about sampling requirements		Date:	07/10/2025
Type: Bradenhead	# 1			
Comment:				
Corrective Action:			Date:	
Type: Prime Mover	# 1			
Comment:	Electric			
Corrective Action:			Date:	
Type: Flow Line	# 3			
Comment:	2 flowlines sticking out of ground by meter house not labeled OOSLT see picture #10			
Corrective Action:	Lock out and tag out capped flowlines per rule 11.02 OSLT		Date:	04/23/2025
Type: Other	# 1			
Comment:	Meter house calibration card is up to date see pictures #7 #8			
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:	One dead man marker laying down see picture #4			
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	OTHER	STEEL AST		37.234544,-107.818613
Comment:	95 bbl partially buried vessel at 37.234544,-107.818613 has been removed, no notice of major change or form 27 in well file				
Corrective Action:	File Form 27 and follow up with SW EPS Jason Kosola about required sampling				Date: 06/10/2025

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	216163	Type:	WELL	API Number:	067-07769	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		01/30/2025		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	480579	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	CL
Producing Well									
Comment:									
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:				Annual Brhd Completed?					
Last Brhd Test Results		Initial Surf Csg Pressure:				Fluid Type:			
		End Surf Csg Pressure:							
Comment:		No bradenhead test date on file						06/10/2025	
Corrective Action:		Test Bradenhead						Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams	Pass					
Waddles	Fail					
		Gravel	Pass			
Gravel	Pass					

Comment: Waddles filled with sediment refer to picture #5

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404167067	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7007173
719000022	Locatin Pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7007166