

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/10/2025

Submitted Date:

04/16/2025

Document Number:

719000020

FIELD INSPECTION FORM

Loc ID: 326613 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

Findings:

- 16 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Huntington, Heather		hhuntington@enduringresources.com	SJB inspections
Walter, Klye		kwalter@enduringresources.com	SJB inspections
Kosola, Jason		jason.kosola@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258994	WELL	PR	01/17/2001	CBM	067-08398	CRADER 2-3	PR

General Comment:

Inspection Report Summary
On 4-10-25 I Inspector Charles Garcia conducted an on-site inspection.
Location: CRADER 2-3
Operator: Enduring resources
API#: 067-08398
County: LaPlata
Separator and partially buried vessel have been removed since last compliance inspection. No Form 42 notice of major change or Form 27s in well file. See Equipment and Tank sections for corrective actions

Location			
Lease Road:			
Type	Access		
comment:	Gravel compacted		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Sign at entrance of location		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	1-800-916-9897		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Dried weed debris noted inside fence corners and perimeter of location outside fencing see pictures #5 #6		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	_____		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	6' chain link fencing with visual barrier and topped with barb wire.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Cattle panels		
Corrective Action:			Date:
Equipment:			
Type: Other	# 1		corrective date
Comment:	Wellhead		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment. Electrical control panel		

Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Meter house calibration card up to date		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 0		
Comment:	Separator has been removed since last compliance inspection. No notice of major change or Form 27 in well file.		
Corrective Action:	Submit Form 27 and follow up with SW EPS Jason Kosola about sampling requirements	Date:	07/10/2025
Type: Other	# 1		
Comment:	Meter house calibration card up to date see pictures #3 #4		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	OTHER	STEEL AST		
Comment:	95 bbl partially buried vessel at has been removed, no notice of major change or form 27 in well file				
Corrective Action:	File Form 27 and follow up with SW EPS Jason Kosola about required sampling				Date: 07/10/2025

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404167072	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7007175
719000023	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7007167