

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2025

Submitted Date:

04/16/2025

Document Number:

713602087**FIELD INSPECTION FORM**Loc ID 321579 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 17180Name of Operator: CITATION OIL & GAS CORPAddress: 14077 CUTTEN RDCity: HOUSTON State: TX Zip: 77069**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Sanchez, Chris		chris.sanchez@state.co.us	
Steffy Goncalves		SGoncalves@cogc.com	
CITATION		ENV-CODNR@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207340	WELL	PR	08/23/2007	OW	017-06275	MCCORMICK 24-3 6	RI

General Comment:

This is a follow up inspection at the MCCORMICK 24-3 #6 wellsite.
See attached photos and additional details within this report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	The excavated area must be fenced off to prevent livestock and wildlife entry.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: During excavation of the previously observed spill on 1/28/2025, another spill was discovered. The Operator will need to submit a new form 19 regarding the recently encountered spill that occurred. At the time of inspection, the open excavation was over 20 feet deep and water started seeping into the hole indicating possible groundwater encountered.

Corrective Action: Report spill or release of E&P waste or produced fluids Remove free fluids and contact ECMC EPS staff per Rule 912.b.

Date: 04/17/2025

Reportable: YES

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Waste Management:

Type Management Condition GPS (Lat) (Long)

Piles

Inadequate

Comment: The excavated material has a plastic liner but has fallen outside of the liner and there is no secondary containment. All E&P waste needs to be stored with a liner and berm or other containment.

Corrective Action: E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 905.

Date: 04/18/2025

Spill/Remediation:

Comment: Previously observed spill on 1/28/2025 has been reported and remains ongoing under project #38695.

Corrective Action:

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404167988	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7008016
713602088	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7008007