

Caerus
17F
Location ID: 335023



Location



Location

Caerus
17F
Location ID: 335023



Location



Location

Caerus
17F
Location ID: 335023



Location



Lack of stabilization/compaction

Caerus
17F
Location ID: 335023



Lack of stabilization/compaction



Erosion on cut slope by tank battery

Caerus
17F
Location ID: 335023



Lack of stabilization/compaction



Lack of stabilization/compaction

Caerus
17F
Location ID: 335023



Staining?



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources