

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/22/2025

Submitted Date:

04/24/2025

Document Number:

708303734

FIELD INSPECTION FORM

Loc ID: 418772 Inspector Name: Morris, Matthew On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 14 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Smelser, Wayne		wayne.smelser@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419320	WELL	PR	01/27/2012	GW	045-19908	Kaufman 32B-24-692	PR
419321	WELL	PR	02/22/2012	GW	045-19909	Kaufman 22D-24-692	PR
419322	WELL	PR	01/27/2012	GW	045-19910	Kaufman 32D-24-692	PR
419323	WELL	PR	02/27/2012	GW	045-19911	Kaufman 21C-24-692	PR
419324	WELL	PR	06/01/2022	GW	045-19912	Kaufman 32C-24-692	PR
419326	WELL	PR	01/27/2012	GW	045-19913	Kaufman 32A-24-692	PR
419327	WELL	SI	01/01/2025	GW	045-19914	Kaufman 22A-24-692	SI
419328	WELL	PR	02/27/2012	GW	045-19915	Kaufman 21D-24-692	PR
419329	WELL	PR	02/27/2012	GW	045-19916	Kaufman 21A-24-692	PR
419330	WELL	PR	12/28/2011	GW	045-19917	Kaufman 31A-24-692	PR
419331	WELL	PR	12/28/2011	GW	045-19918	Kaufman 31D-24-692	PR
419332	WELL	PR	12/28/2011	GW	045-19919	Kaufman 31C-24-692	PR
419334	WELL	PR	02/27/2012	GW	045-19920	Kaufman 21B-24-692	PR
419336	WELL	PR	12/28/2011	GW	045-19921	Kaufman 31B-24-692	PR
419337	WELL	PR	02/22/2012	GW	045-19922	Kaufman 22C-24-692	PR
419339	WELL	PR	01/26/2012	GW	045-19923	Kaufman 22B-24-692	PR

General Comment:

CECMC Audit Report Summary

On 4/22/2025 at approximately 14:00, Compliance Inspector Matthew Morris conducted a follow-up audit at TEP ROCKY MOUNTAIN LLC, Kaufman Pad 6/21A-24-692 at Location ID #418772 in Garfield County, Colorado.

During the audit, the following compliance issues were observed:

- 1) Multiple illegible wellhead signs
- 2) Stored supplies (load hose) poses a wildlife entry hazard
- 3) Unused equipment

A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Multiple illegible wellhead signs.		
Corrective Action:	Install signs to comply with Rule 605.d.	Date:	04/18/2025
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign is weathering but is legible.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/(970)285-9377		
Corrective Action:		Date:	_____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused chemical tank near wellheads.		
Corrective Action:	Remove unused equipment.	Date:	03/25/2025
Type	STORAGE OF SUPL		
Comment:	Stored load hose in tank containment poses a wildlife entry hazard.		
Corrective Action:	Remove/secure stored supplies to prevent wildlife entry.	Date:	04/29/2025
Type	TRASH		
Comment:	Trash on location near wellheads.		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 16		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 15		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 16		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Bradenhead	# 16		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	500 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	500 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

Venting:	
Yes/No	NO

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	419320	Type:	WELL	API Number:	045-19908	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	419321	Type:	WELL	API Number:	045-19909	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	419322	Type:	WELL	API Number:	045-19910	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	419323	Type:	WELL	API Number:	045-19911	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	419324	Type:	WELL	API Number:	045-19912	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	419326	Type:	WELL	API Number:	045-19913	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	419327	Type:	WELL	API Number:	045-19914	Status:	SI	Insp. Status:	SI
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	419328	Type:	WELL	API Number:	045-19915	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 419329 Type: WELL API Number: 045-19916 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 419330 Type: WELL API Number: 045-19917 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 419331 Type: WELL API Number: 045-19918 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 419332 Type: WELL API Number: 045-19919 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 419334 Type: WELL API Number: 045-19920 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 419336 Type: WELL API Number: 045-19921 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 419337 Type: WELL API Number: 045-19922 Status: PR Insp. Status: PR

Producing Well			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	419339	Type:	WELL	API Number:	045-19923	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Slope Roughening						
				Material Handling And Spill Prevention		
		Gravel				
		Check Dams				
Gravel						
Ditches						
Compaction						
		Culverts				
		Ditches				
Berms						

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708303735	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7022063