

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/21/2025

Submitted Date:

04/24/2025

Document Number:

707603855**FIELD INSPECTION FORM**Loc ID 309825 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
172	WELL	TA	02/01/2017	OW	123-25429	LAPP 13-33	TA

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Abandoned. ALL equipment has been removed.
Abandoned Battery SE corner GPS coordinates: 40.483260 / -104.507530

Abandoned Centralized Battery formerly served 7 Location IDs
(309825, 309834, 310801, 306184, 309826, 306139, 419303).
(Well(s): 3: Temporarily Abandoned | TA; 4: Plugged & Abandoned | PA).

Reference (Associated Well(s) Inspections):
A.) Field Inspection Report doc. #707603855 and/or Location ID #309825
for TA Well(s) info.
B.) Field Inspection Report doc. #707603857 and/or Location ID #309834
for TA Well(s) info.
C.) Field Inspection Report doc. #707603859 and/or Location ID #310801
for TA Well(s) info.
D.) Field Inspection Report doc. #707603861 and/or Location ID #306184
for PA Well(s) info.
E.) Field Inspection Report doc. #707603863 and/or Location ID #309826
for PA Well(s) info.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	Posted.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	CORRECTIVE GUIDANCE Item(s): 1.) Weed housekeeping. Overgrown vegetation at wellsite. Refer to Rule 606.c for guidance. See photo #1. *Remove, manage, & control overgrown vegetation around wellsite. Comply with Rule 606.c			
Corrective Action:			Date:	
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Iron panel.			
Corrective Action:			Date:	
Equipment:				
			corrective date	
Type: Bradenhead	# 1			
Comment:	Appears plumbed to surface.			
Corrective Action:			Date:	
Type: Plunger Lift	# 0			
Comment:	Temporarily Abandoned TA. Equipment removed.			
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Wellhead: w/ Master, casing valves.			

Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 172

Type: WELL

API Number: 123-25429

Status: TA

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment:

Temporarily Abandoned | TA.
Battery Abandoned.
ECMC records last production: 4/2016.
Locked-Out, Tagged-Out | LOTO.
OOSLAT, Yellow LTSI tag(s) posted at well.

Form 4 on file. TA date: 01/25/2017. Approved.
RBP-DH.
Form 6A on file. Out-of-Svc Designation.
Date: 10/17/2015. Approved.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/15/2024

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On MON 04/21/2025 at approximately 13:37 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: LAPP-66N64W/13SWSW Location ID: 309825 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.483260 / -104.507530</p> <p>CORRECTIVE GUIDANCE Item(s): 1.) See "Good Housekeeping" section on page 2 of this report.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	04/24/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603856	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7022250