

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/21/2025

Submitted Date:

04/24/2025

Document Number:

707603857

FIELD INSPECTION FORM

Loc ID 309834 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236	WELL	TA	05/26/2020	OW	123-25439	LAPP 13-31	TA

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Abandoned. ALL equipment has been removed.
Abandoned Battery SE corner GPS coordinates: 40.483260 / -104.507530

Abandoned Centralized Battery formerly served 7 Location IDs (309825, 309834, 310801, 306184, 309826, 306139, 419303).
(Well(s): 3: Temporarily Abandoned | TA;4: Plugged & Abandoned | PA).

Reference (Associated Well(s) Inspections):
A.) Field Inspection Report doc. #707603855 and/or Location ID #309825 for TA Well(s) info.
B.) Field Inspection Report doc. #707603857 and/or Location ID #309834 for TA Well(s) info.
C.) Field Inspection Report doc. #707603859 and/or Location ID #310801 for TA Well(s) info.
D.) Field Inspection Report doc. #707603861 and/or Location ID #306184 for PA Well(s) info.
E.) Field Inspection Report doc. #707603863 and/or Location ID #309826 for PA Well(s) info.

Location

Lease Road:			
	Type Access		
	comment: Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type WELLHEAD		
	Comment:		
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: Posted.		
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type WELLHEAD		
	Comment: Iron panel.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
	Comment: Appears plumbed to surface.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
	Comment:		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
	Comment:		
Corrective Action:			Date:

Flaring:			
Type			
	Comment:		
Corrective Action:			Date:

Inspected Facilities

Facility ID: 236 Type: WELL API Number: 123-25439 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Battery Abandoned.
ECMC records last production: 4/2016.
Locked-Out, Tagged-Out | LOTO.
OOSLAT, Yellow LTSI tag(s) posted at well.

Form 4 on file. TA date: 10/26/2016. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 10/17/2015. Approved.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 09/04/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On MON 04/21/2025 at approximately 14:25 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: LAPP-66N64W/13NESW Location ID: 309834 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.483260 / -104.507530</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	04/24/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603858	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7022251