

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/21/2025

Submitted Date:

04/25/2025

Document Number:

707603859

FIELD INSPECTION FORM

Loc ID 310801 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297174	WELL	TA	04/01/2017	OW	123-26999	LAPP 13-35	TA

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Abandoned. ALL equipment has been removed.
Abandoned Battery SE corner GPS coordinates: 40.483260 / -104.507530

Abandoned Centralized Battery formerly served 7 Location IDs (309825, 309834, 310801, 306184, 309826, 306139, 419303).
(Well(s): 3: Temporarily Abandoned | TA;4: Plugged & Abandoned | PA).

Reference (Associated Well(s) Inspections):
A.) Field Inspection Report doc. #707603855 and/or Location ID #309825 for TA Well(s) info.
B.) Field Inspection Report doc. #707603857 and/or Location ID #309834 for TA Well(s) info.
C.) Field Inspection Report doc. #707603859 and/or Location ID #310801 for TA Well(s) info.
D.) Field Inspection Report doc. #707603861 and/or Location ID #306184 for PA Well(s) info.
E.) Field Inspection Report doc. #707603863 and/or Location ID #309826 for PA Well(s) info.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	CORRECTIVE GUIDANCE Item(s): 1.) Weed housekeeping. Overgrown vegetation at wellsite. Refer to Rule 606.c for guidance. See photo #1. *Remove, manage, & control overgrown vegetation around wellsite. Comply with Rule 606.c		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Other	# 1		
Comment:	Wellhead: w/ Master, casing valves.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 297174 Type: WELL API Number: 123-26999 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Battery Abandoned.
ECMC records last production: 2/2017.
Locked-Out, Tagged-Out | LOTO.
Yellow LTSI tag(s) posted at well.

Form 4 on file. TA date: 02/08/2017. Approved.
RBP-DH.
Form 21-MIT on file; MIT date: 02/15/2019. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 01/01/2015. Approved.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 07/15/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On MON 04/21/2025 at approximately 14:12 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: LAPP/13-35 Location ID: 310801 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.483260 / -104.507530</p> <p>CORRECTIVE GUIDANCE Item(s): 1.) See "Good Housekeeping" section on page 2 of this report.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	04/24/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603860	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7022252