

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/21/2025

Submitted Date:

04/25/2025

Document Number:

707603861

**FIELD INSPECTION FORM**

Loc ID 306184 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286142	WELL	PA	12/05/2023	OW	123-24136	LAPP 13-32	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Battery: Abandoned. ALL equipment has been removed.  
Abandoned Battery SE corner GPS coordinates: 40.483260 / -104.507530

Abandoned Centralized Battery formerly served 7 Location IDs (309825, 309834, 310801, 306184, 309826, 306139, 419303).  
(Well(s): 3: Temporarily Abandoned | TA;4: Plugged & Abandoned | PA).

Reference (Associated Well(s) Inspections):  
A.) Field Inspection Report doc. #707603855 and/or Location ID #309825 for TA Well(s) info.  
B.) Field Inspection Report doc. #707603857 and/or Location ID #309834 for TA Well(s) info.  
C.) Field Inspection Report doc. #707603859 and/or Location ID #310801 for TA Well(s) info.  
D.) Field Inspection Report doc. #707603861 and/or Location ID #306184 for PA Well(s) info.  
E.) Field Inspection Report doc. #707603863 and/or Location ID #309826 for PA Well(s) info.

**Inspected Facilities**Facility ID: 286142 Type: WELL API Number: 123-24136 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Synopsis:</b></p> <p>On MON 04/21/2025 at approximately 15:01 hrs. I, Bret Evins, conducted an onsite inspection at:  Operator Name: NOBLE ENERGY INC  Location Name: LAPP-66N64W/13NWSW  Location ID: 306184  Well Name(s) &amp; API:  Reference:  See "Inspected Facilities" section on page 1 of this Field Inspection Report.  Location County: Weld County, Colorado  Weather: Partly Sunny, dry.</p> <p>While there, I observed:  Well(s): 1: Plugged &amp; Abandoned   PA.  Battery: Abandoned. ALL equipment removed.  Abandoned Battery SE corner GPS coordinates: 40.483260 / -104.507530</p> <p><b>WELL STATUS COMMENT:</b>  Plugged &amp; Abandoned   PA.  Form 6-SRA on file. Plugging, cut/cap date: 12/05/2023. Approved.  Plugged &amp; Abandoned   PA well GPS coordinates: 40.484260 / -104.506150</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	04/25/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603862	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7022253">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7022253</a>