

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2025

Submitted Date:

04/25/2025

Document Number:

717300311

FIELD INSPECTION FORM

Loc ID 336390 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206562	WELL	TA	01/01/2024	GW	013-06057	ALCORN 1	PA
294745	WELL	SI	06/01/2022	GW	013-06579	ALCORN 32-10	PA
470269	Location	AC			-	ALCORN-61N69W 10NWNE	EG

General Comment:

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 206562 Type: WELL API Number: 013-06057 Status: TA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294745 Type: WELL API Number: 013-06579 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 470269 Type: Location API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Wells are plugged and abandoned (Alcorn 1, 32-10); ECMC form 42 notice of start of plugging operations doc #404097936 received 02/18/2025. No flowlines/ risers observed at PA well(s) or facility/ battery areas. The facility/ tank battery has been decommissioned; tanks and equipment removed. On location dump and process flowlines at facility/ battery are removed. Remediation work is in progress.	maclarej	04/25/2025
As outlined on COGCC form 19 spill report Doc #404157835 received on 04/08/2025: While conducting facility decommissioning activities at Crestone's Alcorn-61N69W 10NWNE facility, historical impacts were discovered. The impacted soil will be removed and hauled for disposal.	maclarej	04/25/2025
As outlined on COGCC form 19 spill report Doc #404157778 received on 04/08/2025: While conducting facility decommissioning activities at Crestone's Alcorn 1 wellhead, historical impacts were discovered. The impacted soil will be removed and hauled for disposal.	maclarej	04/25/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404179833	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7023334
717300313	PA well and signage	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7023329
717300314	Facility decommissioned; OOS GMR	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7023330