

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 8-30 Pad

Location #: 335280



Photo # 4607 From entrance to location




Photo # 4608 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 8-30 Pad

Location #: 335280



Photo # 4609 Location



Photo # 4610 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 8-30 Pad

Location #: 335280



Photo # 4611 Location



Photo # 4612 Location



Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 8-30 Pad

Location #: 335280



Photo # 4613 Unmarked deadman



Photo # 4614 Same unmarked deadman

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 8-30 Pad

Location #: 335280



Photo # 4615 Same unmarked deadman from another angle




Photo # 4616 Battery sign damaged & some required information is illegible/not in compliance with CECMC rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 8-30 Pad

Location #: 335280




Photo # 4617 GIBSON GULCH 8-30B BH line connected to flowline




Photo # 4618 GIBSON GULCH 8-30B BH line connected to flowline

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 8-30 Pad

Location #: 335280




Photo # 4619 GIBSON GULCH 8-30B well - Ball valve on line connecting BH line to flowline appears to be shut




Photo # 4620 GIBSON GULCH 8-30B well - Ball valve on line connecting BH line to flowline appears to be shut



Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 8-30 Pad

Location #: 335280




Photo # 4621 GIBSON GULCH 8-30B well - Ball valve on line connecting BH line to flowline appears to be shut




Photo # 4622 GIBSON GULCH 8-30B well - Ball valve on line connecting BH line to flowline appears to be shut