

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 13-20A

Location #: 335339



Photo # 4738 From entrance to location




Photo # 4739 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 13-20A

Location #: 335339



Photo # 4740 Location




Photo # 4741 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 13-20A

Location #: 335339



Photo # 4742 Location



Photo # 4743 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 13-20A

Location #: 335339



Photo # 4744 Location



Photo # 4745 Unused hose in secondary containment



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 13-20A

Location #: 335339



**Photo # 4746 Chemical tank disconnected & not in use/  
unused equipment**



**Photo # 4747 Chemical tank disconnected & not in use/  
unused equipment**

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 13-20A

Location #: 335339



**Photo # 4748 Tank label weathered & some required information is illegible/not in compliance with CECMC rules**



**Photo # 4749 Tank label weathered & some required information is illegible/not in compliance with CECMC rules**