

Inspection Photos

API: 043-40001

Operator: JAVERNICK OIL

Inspection Date: 4/25/2025



Inspection Photos



Photo 1. Facing north along the access road. There is an erosion gully along the roadside has been repaired.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. The sediment at the culvert outlet was pushed back in the drainage at red arrow. This material needs to be removed or slope out of the drainage so it does not wash back into the culvert.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing back along the access road. The dozer cut into the embankment to fill in the erosion. The embankment cut now needs to be resloped and stabilized.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. The culvert has been cleaned out and soil and debris is piled up along the side which needs to be removed.



Inspection Photos



Photo 5. Facing northeast at the locations. Soils need to be cross ripped and reseeded.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 6. The oil stained soils still remain at the location. Impacted soils need to be excavated and removed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 7. Facing southeast at the locations. Soils need to be cross ripped and reseeded.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 8. The cement blocks and guy line anchor at this area has been removed.

