

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/28/2025

Submitted Date:

04/28/2025

Document Number:

713302001**FIELD INSPECTION FORM**Loc ID 331738 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Revas, Robbie		robbie.revas@state.co.us	
, KerrMcGee	970-515-1500	ECMCInspections@Oxy.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265357	WELL	SI	02/01/2025	GW	123-21213	DECHANT 12-9A	SI

General Comment:[well site inspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Missing,		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	05/05/2025

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	dead vegation		
Corrective Action:	Comply with Rule 606		Date: 05/05/2025

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	metal panels		
Corrective Action:			Date:

Equipment:				corrective date
Type: Bradenhead	# 1			
Comment:	piped to surface			
Corrective Action:			Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 265357 Type: WELL API Number: 123-21213 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Form 6A on file doc 403108165, 7-22-2022 well head disconnected with fittings plugged

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 05/17/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NoneEnd Surf Csg Pressure: --

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>Inspector Michael Kester, did audit scout card and related documents conducted an on-site inspection, Location: Dechant 12-9A Operator: Kerr McGee API#: 123-21213 County: Weld While there, I observed well site with Form 6A on file doc 403108165, 7-22-2022, well head disconnected with fittings plugged.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Sign, Rule 605d, corrective action date 5-5-2025 photos 1&2 DEAD overgrown vegataion, Rule 606 corrective action date 5-5-2025 photos 1&2</p> <p>Weather conditions: sunny and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This inspection does not nullify any orders or NOAV from the ECMC</p>	kesterm	04/28/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713302002	site pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7026232