

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/27/2025

Submitted Date:

04/28/2025

Document Number:

697602478

**FIELD INSPECTION FORM**

Loc ID 317320 Inspector Name: Ahmadian, Alexander On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 81720  
Name of Operator: STANDLEY\* ROBERT K DBA OTIS ENERGY  
Address: 315 SOUTH VINE STREET  
City: OTIS State: CO Zip: 80743

**Findings:**

- 6 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Waggoner, Kyle		kyle.waggoner@state.co.us	
Ellen Standley		venture2.es@gmail.com	
Heibel, Krystal		krystal.heibel@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
103432	PIT	AC			-	GOEGLEIN 5 PIT 2	EI
103433	PIT	AC			-	GOEGLEIN 5 PIT 3	EI
112603	PIT	AC			-	GOEGLEIN 5 PIT 1	EI
238071	WELL	SI	01/01/2018	OW	121-10574	GEOGLEIN 5	EI
317320	LOCATION	AC			-	GEOGLEIN-62N49W 13SWSE	EI

**General Comment:**

ECMC Environmental Inspection to determine progress on GEOGLEIN-62N49W 13SWSE #1 (Location ID: 317320). Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Operator Name: STANDLEY\* ROBERT K DBA OTIS ENERGY  
Location Name: GEOGLEIN-62N49W 13SWSE #1  
API: 05-121-10574 Location ID: 317320  
County: Washington County, Colorado

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		
Comment: Hydrocarbon impacted soils observed on location. Soil used to backfill the PIT has observable stained soil.				
Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.  In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.			Date: 06/26/2024	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>		corrective date
Type:	#	
Comment: No equipment left on location. Evidence of facility abandonment. No Site Investigation and Remediation Workplan (Form 27) submitted to the ECMC.		
Corrective Action: Operator shall submit a Site Investigation and Remediation Workplan (Form 27) that includes a specific workplan and timeline to address the remaining impacts, detailing the plans to decommission this facility in accordance with the 900 series rules.		Date: 06/26/2024

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment: Tank battery removed since last inspection. Evidence of facility abandonment. No Site Investigation and Remediation Workplan (Form 27) submitted to the ECMC since last inspection.					
Corrective Action: Operator shall submit a Site Investigation and Remediation Workplan (Form 27) that includes a specific workplan and timeline to address the remaining impacts, detailing the plans to decommission this facility in accordance with the 900 series rules.					Date: 06/26/2024

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 103432 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 103433 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 112603 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 238071 Type: WELL API Number: 121-10574 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 317320 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: No Remediation Workplan (Form 27) has been submitted addressing the remediation efforts performed at the site.

Corrective Action: Operator shall submit a Site Investigation and Remediation Workplan (Form 27) that includes a specific workplan and timeline to address the remaining impacts, detailing the plans to decommission this facility in accordance with the 900 series rules. Date: 06/26/2024

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment:

[No Site Investigation and Remediation Workplan \(Form 27\) submitted to the ECMC.](#)

Corrective Action: \_\_\_\_\_

[Operator shall submit a Site Investigation and Remediation Workplan \(Form 27\) detailing the plans to decommission this facility in accordance with the 900 series rules.](#)

Date: 06/26/2024

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697602479	Photolog	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7027038">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7027038</a>