

Inspection Photos
Location Name: UIV 18-20
Location ID: 306059



Plugging operations



Wellhead sign