

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/30/2025

Submitted Date:

04/30/2025

Document Number:

715801178

FIELD INSPECTION FORM

Loc ID 317800 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 17 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239993	WELL	PR	02/01/2019	OW	123-07781	1415 CORP GAS UNIT B 1	SI
451454	TANK BATTERY	AC	07/21/2017		-	1415 Corp Gas Unit B1 battery	AC

General Comment:

[This is a wellsite & tank battery file audit followed by a field inspection.](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	The sign faded and shall be replaced, Comply with Rule 605.g. CA date 5-30-2025.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Placards are peeling & faded and shall be replaced, Comply with Rule 605.h. CA date 5-30-2025.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	the sign is faded and shall be replaced, Comply with Rule 605.g. CA date 5-30-2025.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Gas meter run-Ag panel		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Ag panel		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	wire & wood post		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Ag panel		
Corrective Action:			Date:

Equipment:			
Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:			Date:

Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:	Flow line manifold		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Card indicates that the meter needs to be calibrated, Comply with Rule 430. CA date 5-30-2025		
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	automation		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.133000,-104.865000
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	FIBERGLASS AST		,
Comment:					

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth					
Comment: shares containment with crude tank					
Corrective Action:					Date:

Wells Served By Facilities Above

API Number
123-07781

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO			
Comment:				
Corrective Action:			Date:	

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 239993 Type: WELL API Number: 123-07781 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI valve are closed Electric panel is off

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/07/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451454 Type: TANK API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Monday 4-30-2025 at approximately 1210 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card & related forms followed by an onsite inspection: Operator:KP Kauffman Location # 317800 API #05-123-07781 Well name: 1415 Corp Gas Unit B1 County: Weld Weather: Cloudy & clear Temp: 70 Location: dry While there, I observed wellsite & tank battery, SI at the time of inspection. During this inspection the following possible compliance issues were observed: Signs 605.g & 605.h: CA date 5-30-2025. 430 measurment of oil & gas: CA date 5-30-2025. See attached photos. A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	04/30/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715801179	Location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7029766