

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/01/2025

Submitted Date:

05/02/2025

Document Number:

715202303

FIELD INSPECTION FORM

Loc ID 324785 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10017
Name of Operator: CHACO ENERGY COMPANY
Address: P O BOX 1587
City: DENVER State: CO Zip: 80201

Findings:

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Nelson, Matt		matt@chacoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212573	WELL	PR	07/01/2003	GW	061-05024	STATE 1-16	PR

General Comment:

SE Compliance Specialist Brian Welsh conducted an audit and routine field inspection of the well location and equipment

Location

Lease Road:			
Type	Access		
comment:	Two track through pasture		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Stickers and stencils on tank. NFPA label is faded and needs replaced		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign mounted to fence at tank battery isn't legible		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	06/01/2025

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Pipe fence around meter shed		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Metal panels around separator		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Wire fence around tank battery		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	Meter shed on south side of HHS		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1	
Comment:	HHS on west side of tank	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	<100 BBLs	STEEL AST		38.319350,-102.795520
Comment:	90bbl steel production tank				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 212573 Type: WELL API Number: 061-05024 Status: PR Insp. Status: PR

Producing Well

Comment: [Production. Production reports are up to date at time of inspection](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: [Location and access are grassed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715202312	location photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7033154