

Interim Reclamation and Stormwater Inspection

April 30, 2025

Operator: PONCHO PRODUCTION COMPANY - 71450

Location ID: 316972

Well Name: JOLLY #D-1

Inspection Document #: 718600551

Washington County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: JOLLY #D-1
Location ID: 316972



Photo 1. Looking west down access road to tank battery.



Photo 2. Looking North across the tank battery location. Soil pile on west side of location (red circle). Soil pile has some vegetation growing on it but is largely bare soil.



Inspection Photos
Location Name: JOLLY #D-1
Location ID: 316972



Photo 3. Former separator base to the south of the tank battery. Debris is present around base.




Photo 4. Looking north across the tank battery. Debris is present throughout location (buckets, metal). Fence around tank battery is down and it appears cows have been entering the tank battery.



Inspection Photos
Location Name: JOLLY #D-1
Location ID: 316972



Photo 5. Looking south down the west side of the tank battery. The interim area outside of the tank battery appears to be desirable perennial vegetation.



Photo 6. Looking east down the north side of the tank battery. see photo 5 comments.



Inspection Photos
Location Name: JOLLY #D-1
Location ID: 316972



Photo 7. Looking east across the skim pit located to the east of the tank battery. The barbed wire fence around the pit is down and livestock appears to be entering the pit and drinking from standing water in the pit/ evaporation pond.



Inspection Photos
Location Name: JOLLY #D-1
Location ID: 316972



Photo 8. Skim pit on the west side of pond. Cattle prints are present in the mud at bottom.



Photo 9. Looking north across skim pit on the west side of the pond.



Inspection Photos
Location Name: JOLLY #D-1
Location ID: 316972



Photo 10. Looking east across the evaporation pond. Debris remains in the pond. Standing water is present in the pond at the time of inspection. Cattle tracks are present at the water's edge.



Photo 11. Picture taken on the east side of the evaporation pond looking south. Pipe remains in and around the berm (red circles).



Inspection Photos
Location Name: JOLLY #D-1
Location ID: 316972



Photo 12. Looking west along the southern edge of the evaporation pond. Soil pile is present on the south side of tank battery (red circle). Soil pile is primarily bare soil with little vegetation coverage.



Photo 13. Looking west across the well location. Location size has been reduced and desirable perennial vegetation has established around the location. Undesirable weeds such as Kochia are present inside the fence.



Inspection Photos
Location Name: JOLLY #D-1
Location ID: 316972



Photo 14. Looking east down the north side of the well location. Debris and unused equipment is present (belt cover, posts, barbed wire, sucker rod, pipe)



Photo 15. Pipe stored on the north side of location.

