

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2025

Submitted Date:

05/01/2025

Document Number:

699507197

FIELD INSPECTION FORM

Loc ID 469568	Inspector Name: MEDINA, JUSTIN	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 7 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: ECMC Operator Number: 10651 Name of Operator: VERDAD RESOURCES LLC Address: 1125 17TH STREET SUITE 600 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
,		Regulatory@verdadoil.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
470222	WELL	PR	07/01/2024	OW	123-50669	Safi 1224-12H	PR
470223	WELL	PR	07/01/2024	OW	123-50670	Safi 1224-02H	PR
470224	WELL	PA	10/10/2023	OW	123-50671	Safi 1224-10H	PA
470225	WELL	PR	07/01/2024	OW	123-50672	Safi 1224-14H	PR
470226	WELL	PR	05/01/2024	OW	123-50673	Ramen 1423 02H	PR
470227	WELL	PR	05/01/2024	OW	123-50674	Ramen 1423 03H	PR
470228	WELL	PR	05/01/2024	OW	123-50675	Ramen 1423 04H	PR
470229	WELL	PR	07/01/2024	OW	123-50676	Safi 1224-08H	PR
470230	WELL	PR	07/01/2024	OW	123-50677	Safi 1224-06H	PR
470231	WELL	PR	05/01/2024	OW	123-50678	Ramen 1423 05H	PR
470232	WELL	PR	05/01/2024	OW	123-50679	Ramen 1423 06H	PR
470233	WELL	PR	07/01/2024	OW	123-50680	Safi 1224-04H	PR
470234	WELL	PR	05/01/2024	OW	123-50681	Ramen 1423 07H	PR
470235	WELL	PR	05/01/2024	OW	123-50682	Ramen 1423 01H	PR
472995	SPILL OR RELEASE	CL	04/06/2020		-	Safi 1224	CL
485611	WELL	PR	05/01/2024	OW	123-52352	Ramen 1423 08H	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

Equipment:

corrective date

Type: VRU # 4

Comment:

Corrective Action:

Date:

Type: Emission Control Device # 1

Comment:

Corrective Action:

Date:

Type: Horizontal Separator # 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment: Electric / automation

Corrective Action:

Date:

Type: Bird Protectors # 6

Comment:

Corrective Action:

Date:

Type: Pig Station # 1

Comment:

Corrective Action:

Date:

Type: LACT # 1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run # 1

Comment:

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 14		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 14		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	500 BBLs	STEEL AST		,	
Comment:	538 BBL					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	500 BBLs	FIBERGLASS AST		,	
Comment:	538 BBL					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				

Comment:	shares containment with oil tanks		
Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	470222	Type:	WELL	API Number:	123-50669	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	470223	Type:	WELL	API Number:	123-50670	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	470224	Type:	WELL	API Number:	123-50671	Status:	PA	Insp. Status:	PA
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	470225	Type:	WELL	API Number:	123-50672	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	470226	Type:	WELL	API Number:	123-50673	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	470227	Type:	WELL	API Number:	123-50674	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	470228	Type:	WELL	API Number:	123-50675	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	470229	Type:	WELL	API Number:	123-50676	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	470230	Type:	WELL	API Number:	123-50677	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	470231	Type:	WELL	API Number:	123-50678	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	470232	Type:	WELL	API Number:	123-50679	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	470233	Type:	WELL	API Number:	123-50680	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	470234	Type:	WELL	API Number:	123-50681	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	470235	Type:	WELL	API Number:	123-50682	Status:	PR	Insp. Status:	PR
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	472995	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	CL
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	485611	Type:	WELL	API Number:	123-52352	Status:	PR	Insp. Status:	PR

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

BradenHead			
Date of Last Brhd Test:	07/03/2024		Annual Brhd Completed? Yes
Last Brhd Test Results	Initial Surf Csg Pressure:	1	Fluid Type:
	End Surf Csg Pressure:	0	
Comment:			
Corrective Action:			Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
This inspection does not nullify any orders or corrective actions from the ECMC At time of inspection weather conditions were warm, calm, clear.	medinaj	05/01/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699507198	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7034445