

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-W-19
Location ID: 311567



**Location Overview: Location is within High Priority/Density Habitat areas. Location is approximately 140 yards from a creek/drainage that contributes to the Colorado River.
Section/Township/Range: 19 6S94W**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-W-19
Location ID: 311567



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-W-19
Location ID: 311567



Photo # 7703 Lack of stabilization/compaction



Photo # 7704 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-W-19
Location ID: 311567



Photo # 7705 Lack of stabilization/compaction



Photo # 7706 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-W-19
Location ID: 311567



Photo # 7707 Lack of stabilization/compaction



Photo # 7708 Lack of stabilization/compaction