

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/01/2025

Submitted Date:

05/04/2025

Document Number:

708906406

FIELD INSPECTION FORM

Loc ID: 311567 Inspector Name: Smelser, Wayne On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

25 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
TEP		COGCCInspectionReports@terraep.com	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210900	WELL	PR	12/01/1990	GW	045-06658	DOE 1-W-19	PR

General Comment:

[CECMC Inspection/Audit Report Summary](#)
On 05/01/2025 at approximately 13:04 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC DOE 1-W-19 Pad Location # 311567 in Garfield County Colorado.
Location is within High Priority/Density Habitat areas.
Location is approximately 140 yards from a creek/drainage that contributes to the Colorado River.
While there, I observed normal production operations.

This is a summary of inspection/audit report.

Dual lease, shared pad with the DOE 1-M-19, location # 311545

Location

Lease Road:			
	Type Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type BATTERY		
Comment:	Battery sign weathered & cracking but still legible at this time		
Corrective Action:			Date:
	Type OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: 911/970-285-9377		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
	Type TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:
	Type SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:

Equipment:		corrective date
Type: Plunger Lift	# 0	
Comment:	Well is not on plunger lift	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	Taylor plug located on bradenhead, bradenhead valve is accessible	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:	DOE 1-M-19	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:	DOE 1-M-19	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:	DOE 1-M-19	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Trailer for workover rig located on nearby pad	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLS	STEEL AST		,
Comment:	1 of 2 tanks is equipped with telemetry				

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment: Centralized containment				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		
Comment: Tanks equipped with telemetry					
Corrective Action:					Date:

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment: Centralized containment				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 210900 Type: WELL API Number: 045-06658 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well is not on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						
Check Dams						
Ditches						
		Gravel				Sparse to none in most areas
Rip Rap						
		Compaction				
Gravel						Sparse to none in most areas
		Culverts				
Sediment Traps						
Compaction	Fail					Lack of stabilization/compaction near tank battery

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Signs/Marker & Stormwater for comments	smelserw	05/04/2025
Dual lease, shared pad with the DOE 1-M-19, location # 311545		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708906408	Inspection/Audit 708906406 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7034606
708906409	Inspection/Audit 708906406 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7034607