

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/28/2025

Submitted Date:

04/28/2025

Document Number:

715501645

FIELD INSPECTION FORM
 Loc ID 316493 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num:
Operator Information:

ECMC Operator Number: 6720

Name of Operator: ROBERT L BAYLESS PRODUCER LLC

Address: 707 17TH STREET SUITE 2975

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

16 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|-------------------------|---------|
| Trujillo, Helen | (505) 326-2659 | htrujillo@rlbayless.com | |
| Wilson, Justin | (970) 878-3825 | jrwilson@blm.gov | |
| Thomas, John | (505) 326-2659 | jthomas@rlbayless.com | |
| , Inspections | (505) 326-2659 | notices@rlbayless.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 282381 | WELL | PR | 08/01/2020 | GW | 103-10668 | WEAVER RIDGE 23-14 | PR |

General Comment:**ECMC Inspection Report Summary**

On Monday, 04/28/2025, Inspector Kirby Burchett, was on location for a routine field inspection at Robert L Bayless Producer LLC on the Weaver Ridge 23-14 well, Location #316493, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Colorado Parks and Wildlife (CPW) District and Black Bear area with High Priority and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Location is shared with the Weaver Ridge 23-15 well, Location #316466 including a heater treater and tank battery. While on location during normal operations the following compliance issues were observed:

1. Debris
2. Oily waste and stained soil
3. Faded chemical label

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|---|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Sign incomplete. Corrective Action addressed in Insp. #715501643 on 4/28/25. | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Damaged and missing information. Corrective Action addressed in Insp. #715501643 on 4/28/25. | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | Faded and illegible label Corrective Action addressed in Insp. #715501643 on 4/28/25. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 505-326-2659

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | DEBRIS | | |
| Comment: | Random debris | | |
| Corrective Action: | All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground. | Date: | 05/06/2025 |

Overall Good: ☐**Spills:**

| | | | | |
|--------------------|--|--------|------------|--|
| Type | Area | Volume | | |
| Lube Oil | Pump Jack | | | |
| Comment: | Oily waste and stained soil | | | |
| Corrective Action: | Remove and properly dispose of oily waste, stained and/or contaminated soil. | Date: | 05/14/2025 | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|----------------|-------|--|
| Type | PUMP JACK | | |
| Comment: | Livestock wire | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|------------------|-----|--|-----------------|
| Type: Bradenhead | # 1 | | corrective date |
|------------------|-----|--|-----------------|

| | | | |
|--|-----|--|-------|
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 1 | | |
| Comment: Chemicxal tank on containment | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heater Treater | # 1 | | |
| Comment: 2 wells | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: 2 wells | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER | 1 | 400 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|--------|
| Earth | Adequate | | | | |
| Comment: Unlined | | | | | |
| Corrective Action: | | Date: | | | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 4 | 400 BBLs | STEEL AST | | , |

| | | | | | | |
|--------------------|---|---------------------|---------------------|-------------|-------|--|
| Comment: | Open end tank valves. Corrective Action addressed in Insp. #715501643 on 4/28/25 | | | | | |
| Corrective Action: | | | | | Date: | |
| Paint | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| Berms | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Earth | Adequate | | | | | |
| Comment: | Unlined | | | | | |
| Corrective Action: | | | | | Date: | |
| Venting: | | | | | | |
| Yes/No | NO | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Flaring: | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|---------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 282381 | Type: | WELL | API Number: | 103-10668 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | February 2025 Production Report | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Ditches | | | | | | |
| | | | | Material Handling And Spill Prevention | | |

Comment: [Operator is responsible for maintaining Best Management Practices \(BMPs\) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404182172 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7026469 |
| 715501646 | Inspection Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7026467 |