

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/16/2025

Submitted Date:

04/28/2025

Document Number:

718100500

**FIELD INSPECTION FORM**

Loc ID 414152	Inspector Name: Trujillo, Aaron	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 8 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																
<b>Operator Information:</b> ECMC Operator Number: 10844 Name of Operator: QB ENERGY OPERATING LLC Address: 1001 17TH STREET SUITE 1600 City: DENVER State: CO Zip: 80202				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>																
<b>Contact Information:</b> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>,</td> <td></td> <td>ecmc.inspections@qb-energy.com</td> <td></td> </tr> </table>					Contact Name	Phone	Email	Comment	,		ecmc.inspections@qb-energy.com									
Contact Name	Phone	Email	Comment																	
,		ecmc.inspections@qb-energy.com																		
<b>Inspected Facilities:</b> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> <tr> <td>414152</td> <td>LOCATION</td> <td>AC</td> <td></td> <td></td> <td>-</td> <td>Rulison 17M Pad</td> <td>RI</td> </tr> </table>					Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	414152	LOCATION	AC			-	Rulison 17M Pad	RI
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status													
414152	LOCATION	AC			-	Rulison 17M Pad	RI													
<b>General Comment:</b> <p>On 4/16/2025, Western Reclamation Work Lead Trujillo, and Reclamation Supervisor Arthur conducted an interim reclamation and stormwater inspection at QB Energy LLC's Rulison/17M Pad location in Garfield County, Colorado.</p> <p>Location is within the following High Priority Habitats: Aquatic Sportfish Management Waters; Elk Migration Corridor; Elk Production Area;</p> <p>The following compliance issues were observed during this inspection: -Stormwater</p> <p>Refer to the Location, Reclamation and Stormwater sections of this inspection report for additional details.</p> <p>Refer to the photo-documentation attached to this report.</p> <p>Any corrective action(s) from previous inspection that have not been addressed are still applicable.</p>																				

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Operator label at signage for the Double B Ranch 18-44B well has peeled off. Maintenance advised.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	1-866-662-5304		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	4-strand Barbed wire Fence along the perimeter shows signs of disrepair. Maintenance advised		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle Panels		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	<u>414152</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>RI</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_

Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND, TIMBER

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? <u>Pass</u>	Production areas stabilized ? <u>In</u>
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____	Subsidence over on drill pit? _____
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? <u>In</u>	
Production areas have been stabilized? <u>In</u>	Segregated soils have been replaced? <u>Pass</u>
<b>RESTORATION AND REVEGETATION</b>	
<u>Cropland</u>	
Top soil replaced _____	Recontoured _____ Perennial forage re-established _____
<u>Non-Cropland</u>	
Top soil replaced <u>Pass</u>	Recontoured <u>Pass</u> 80% Revegetation <u>In</u>
1003e. INTERIM VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	
1003 f. Weeds Noxious weeds? <u>I</u>	
Comment	<div style="border: 1px solid black; padding: 5px;"> <p>It was observed in this inspection that the Location has been reduced to areas reasonably needed for production; Interim areas have been recontoured/regraded and vegetation appears to be progressing towards ECMC 1003 uniform desirable perennial requirements.</p> <p>Noxious Weed Rosettes were observed in low densities within interim areas. Ongoing weed monitoring/management efforts advised to ensure Location remains in compliance with 1003.e and 606.c requirements.</p> </div>
Corrective Action	<div style="border: 1px solid black; height: 20px; width: 100%;"></div>
Date _____	
Overall Interim Reclamation <u>In Process</u>	
<b><u>Final Reclamation/ Abandoned Location:</u></b>	
Date Final Reclamation Started: _____	Date Final Reclamation Completed: _____
Final Land Use: <u>RANGELAND, TIMBER</u>	
Reminder: _____	
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____
Debris removed _____	No disturbance /Location never built _____
Access Roads _____	Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____	
Location and associated production facilities reclaimed _____	Locations, facilities, roads, recontoured _____
Compaction alleviation _____	Dust and erosion control _____
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____
1004.d. FINAL VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	

Comment:		
Corrective Action:		Date
Overall Final Reclamation	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps	Fail					
Compaction	In Process					Working Pad Surface

Comment: It was observed in this inspection that the outlet at the sediment trap on the west end of the Location is in disrepair; erosion and degradation is evident. BMP has not been installed or maintained in proper functioning condition.

BMPs to stabilize the working pad surfaces of the well and tank battery facilities show sign of disrepair; degradation/tracking/rutting is evident. Maintenance advised.

Corrective Action: Comply with Rule 1002.f- Install or repair required stormwater and erosion control BMPs in accordance with good engineering practices, and ensure BMPs are maintained in a proper functioning condition.

Date: 05/05/2025

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404182160	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7026431">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7026431</a>
718100501	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7026425">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7026425</a>