

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31A-20-691 Pad

Location ID: 335173




Photo # 8360 From entrance to location

Photo # 8361 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31A-20-691 Pad

Location ID: 335173



Photo # 8362 Location



Photo # 8363 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31A-20-691 Pad

Location ID: 335173



May 1, 2025 at 4:01:06 PM
CO



May 1, 2025 at 4:09:42 PM
CO

Photo # 8364 Location

Photo # 8365 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31A-20-691 Pad

Location ID: 335173



May 1, 2025 at 4:04:25 PM
CO



May 1, 2025 at 4:10:36 PM
CO

Photo # 8366 Location

Photo # 8367 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31A-20-691 Pad

Location ID: 335173



Photo # 8368 Unused flowlines at separators lack lockout tagout (OOSLAT)



Photo # 8369 Unused flowlines at separators lack lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31A-20-691 Pad

Location ID: 335173



Photo # 8370 Unused flowline at tank battery lacks lockout tagout (OOSLAT)



Photo # 8371 Unused flowline at tank battery lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31A-20-691 Pad

Location ID: 335173



Photo # 8372 Unused flowline at wellhead lacks lockout tagout (OOSLAT) (Additionally the flowline is open ended & constitutes a wildlife hazard - JOLLEY 31A)



Photo # 8373 Unused flowline at wellhead lacks lockout tagout (OOSLAT) (Additionally the flowline is open ended & constitutes a wildlife hazard - JOLLEY 31A)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31A-20-691 Pad

Location ID: 335173



Photo # 8374 PRV & Rupture disc vent lines do not comply with CECMC pressure safety device rules



Photo # 8375 PRV & Rupture disc vent lines do not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31A-20-691 Pad

Location ID: 335173



Photo # 8376 Open ended piping/wildlife hazard/available for entry by wildlife



Photo # 8377 Open ended piping/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31A-20-691 Pad

Location ID: 335173



Photo # 8378 Secondary containment insufficient/does not comply with CECMC rules



Photo # 8379 Secondary containment insufficient/does not comply with CECMC rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 31A-20-691 Pad

Location ID: 335173




Photo # 8380 Tank capacity incorrect

Photo # 8381 Tank capacity