

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 20-6 Pad

Location ID: 335185



Photo # 8502 From entrance to location




Photo # 8503 Location



Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 20-6 Pad

Location ID: 335185



Photo # 8504 Location



Photo # 8505 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 20-6 Pad

Location ID: 335185



Photo # 8506 Location



Photo # 8507 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 20-6 Pad

Location ID: 335185



Photo # 8508 Location




Photo # 8509 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 20-6 Pad

Location ID: 335185



May 1, 2025 at 4:37:37 PM
CO



May 1, 2025 at 4:35:52 PM
CO

Photo # 8510 Location

Photo # 8511 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 20-6 Pad

Location ID: 335185



Photo # 8512 Open ended load line



Photo # 8513 Wellhead cellar lacks wildlife egress - JOLLEY #1 (20-6)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 20-6 Pad

Location ID: 335185



**Photo # 8514 Open ended plastic piping/wildlife hazard
/available for entry by wildlife**



**Photo # 8515 Open ended plastic piping/wildlife hazard
/available for entry by wildlife**

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 20-6 Pad

Location ID: 335185



Photo # 8516 PRV & Rupture disc vent lines do not comply with CECMC pressure safety device rules



Photo # 8517 PRV & Rupture disc vent lines do not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 20-6 Pad

Location ID: 335185



Photo # 8518 PRV & Rupture disc vent lines do not comply with CECMC pressure safety device rules



Photo # 8519 PRV & Rupture disc vent lines do not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 20-6 Pad

Location ID: 335185



Photo # 8520 PRV & Rupture disc vent lines do not comply with CECMC pressure safety device rules



Photo # 8521 PRV & Rupture disc vent lines do not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 20-6 Pad

Location ID: 335185



Photo # 8522 Unused flowlines at separators do not comply with general safety rules or lockout tagout rules (OOSLAT)



Photo # 8523 Unused flowline at separators does comply with general safety rules or lockout tagout rules (OOSLAT)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC JOLLEY 20-6 Pad

Location ID: 335185



Photo # 8524 Unused flowline at separators does comply with general safety rules or lockout tagout rules (OOSLAT)



Photo # 8525 Debris laying on the ground near bear proof trash container