

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14MV Pad

Location ID: 335234



Photo # 8895 From entrance to location



Photo # 8896 Location

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14MV Pad

Location ID: 335234



Photo # 8897 Location



Photo # 8898 Location

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14MV Pad

Location ID: 335234



Photo # 8899 Location



Photo # 8900 Location

**Inspection Photos**  
**Location Name: MUSTANG RESOURCES LLC Mead 24-14MV Pad**  
**Location ID: 335234**



**Photo # 8901 Location**



**Photo # 8902 Location**

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14MV Pad

Location ID: 335234



**Photo # 8903 Tank failure – Multiple holes in 210 bbl production tank/tank lacks integrity (Additionally the holes also constitute a wildlife hazard)**



**Photo # 8904 Tank failure – Multiple holes in 210 bbl production tank/tank lacks integrity (Additionally the holes also constitute a wildlife hazard)**

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14MV Pad

Location ID: 335234



**Photo # 8905 Tank failure – Multiple holes in 210 bbl production tank/tank lacks integrity (Additionally the holes also constitute a wildlife hazard)**

**Photo # 8906 Tank failure – Multiple holes in 210 bbl production tank/tank lacks integrity (Additionally the holes also constitute a wildlife hazard)**

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14MV Pad

Location ID: 335234



**Photo # 8907 Tank failure – Multiple holes in 210 bbl production tank/tank lacks integrity (Additionally the holes also constitute a wildlife hazard)**



**Photo # 8908 Tank failure – Multiple holes in 210 bbl production tank/tank lacks integrity (Additionally the holes also constitute a wildlife hazard)**

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14MV Pad

Location ID: 335234



Photo # 8909 Dead bird in secondary containment



Photo # 8910 Dead bird in secondary containment

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14MV Pad

Location ID: 335234



Photo # 8911 Improperly marked deadman



Photo # 8912 Same improperly marked deadman

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14MV Pad

Location ID: 335234



Photo # 8913 Improperly marked deadman



Photo # 8914 Same improperly marked deadman