

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/27/2025

Submitted Date:

04/28/2025

Document Number:

697602478

FIELD INSPECTION FORMLoc ID 317320 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 81720

Name of Operator: STANDLEY* ROBERT K DBA OTIS ENERGY

Address: 315 SOUTH VINE STREET

City: OTIS State: CO Zip: 80743

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Waggoner, Kyle		kyle.waggoner@state.co.us	
Ellen Standley		venture2.es@gmail.com	
Heibel, Krystal		krystal.heibel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
103432	PIT	AC			-	GOEGLEIN 5 PIT 2	EI
103433	PIT	AC			-	GOEGLEIN 5 PIT 3	EI
112603	PIT	AC			-	GOEGLEIN 5 PIT 1	EI
238071	WELL	SI	01/01/2018	OW	121-10574	GOEGLEIN 5	EI
317320	LOCATION	AC			-	GOEGLEIN-62N49W 13SWSE	EI

General Comment:

ECMC Environmental Inspection to determine progress on GEOGLEIN-62N49W 13SWSE #1 (Location ID: 317320). Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Operator Name: STANDLEY* ROBERT K DBA OTIS ENERGY

Location Name: GEOGLEIN-62N49W 13SWSE #1

API: 05-121-10574 Location ID: 317320

County: Washington County, Colorado

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
Comment:	Hydrocarbon impacted soils observed on location. Soil used to backfill the PIT has observable stained soil.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.			Date: 06/26/2024

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type:	#		corrective date
Comment:	No equipment left on location. Evidence of facility abandonment. No Site Investigation and Remediation Workplan (Form 27) submitted to the ECMC.		
Corrective Action:	Operator shall submit a Site Investigation and Remediation Workplan (Form 27) that includes a specific workplan and timeline to address the remaining impacts, detailing the plans to decommission this facility in accordance with the 900 series rules.		
			Date: 06/26/2024

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:	Tank battery removed since last inspection. Evidence of facility abandonment. No Site Investigation and Remediation Workplan (Form 27) submitted to the ECMC since last inspection.					
Corrective Action:	Operator shall submit a Site Investigation and Remediation Workplan (Form 27) that includes a specific workplan and timeline to address the remaining impacts, detailing the plans to decommission this facility in accordance with the 900 series rules.					Date: 06/26/2024

Paint

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date: <input type="text"/>

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	103432	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	103433	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	112603	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	238071	Type:	WELL	API Number:	121-10574	Status:	SI	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	317320	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental			
Spills/Releases:			
Type of Spill: _____		Estimated Spill Volume: _____	
Comment:	No Remediation Workplan (Form 27) has been submitted addressing the remediation efforts performed at the site.		
Corrective Action:	Operator shall submit a Site Investigation and Remediation Workplan (Form 27) that includes a specific workplan and timeline to address the remaining impacts, detailing the plans to decommission this facility in accordance with the 900 series rules.		Date: 06/26/2024
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____	Depth to Ground Water: _____		
Water Well Complaint:			
DWR Receipt Num: _____		Owner Name: _____	GPS : _____
Lat _____ Long _____			
Field Parameters:			
Sample Location: _____ Comment: _____			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
Reference Point: <input type="text"/>	Other: <input type="text"/>	Length: <input type="text"/>	Width: <input type="text"/>	

Lining:Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: Fencing Condition: Comment:

Evidence of pit closure/abandonment. Pit has been backfilled. The pit soil is unconsolidated, and the soil must be packed down. Backhoe is on location, however there were no personnel on location at the time of the inspection.

No Site Investigation and Remediation Workplan (Form 27) submitted to the ECMC.

Corrective Action:

Operator shall submit a Site Investigation and Remediation Workplan (Form 27) detailing the plans to decommission this facility in accordance with the 900 series rules.

Date: 06/26/2024

Netting:Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action: Date: **Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404183166	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7027046
697602479	Photolog	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7027038