

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/05/2025

Submitted Date:

05/06/2025

Document Number:

708906422

FIELD INSPECTION FORM

Loc ID 323901 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: 400130017

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 44 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
TEP		COGCCInspectionReports@terraep.com	
Andrews, Doug		doug.andrews@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211129	WELL	PR	12/23/1994	GW	045-06888	SAVAGE RMV 15-35	PR
421918	WELL	PR	12/26/2012	GW	045-20449	Savage RWF 343-34	PR
421919	WELL	PR	09/13/2012	GW	045-20450	Savage RWF 312-35	PR
421920	WELL	PR	12/14/2012	GW	045-20451	Savage RWF 542-34	PR
421921	WELL	PR	09/13/2012	GW	045-20452	Savage RWF 42-34	PR
421922	WELL	PR	06/01/2024	GW	045-20453	Savage RWF 522-35	PR
421923	WELL	SI	05/01/2024	GW	045-20454	Savage RWF 323-35	SI
421924	WELL	PR	10/12/2012	GW	045-20455	Savage RWF 422-35	PR
421925	WELL	PR	09/13/2012	GW	045-20456	Savage RWF 441-34	PR
421926	WELL	PR	10/12/2012	GW	045-20457	Savage RWF 342-34	PR
421927	WELL	PR	10/12/2012	GW	045-20458	Savage RWF 442-34	PR
421928	WELL	PR	12/14/2012	GW	045-20459	Savage RWF 22-35	PR
421929	WELL	PR	09/30/2012	GW	045-20460	Savage RWF 23-35	PR
421930	WELL	PR	12/26/2012	GW	045-20461	Savage RWF 412-35	PR
421931	WELL	PR	09/13/2012	GW	045-20462	Savage RWF 12-35	PR
422119	WELL	PR	01/01/2013	GW	045-20492	Savage RWF 313-35	PR
422187	WELL	PR	12/26/2012	GW	045-20520	Savage RWF 413-35	PR

General Comment:

CECMC Inspection/Audit Report Summary

On 05/05/2025 at approximately 9:26 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC SAVAGE RMV 15-35 Pad

Location # 323901 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area & Bald Eagle Roost Site.

Location is approximately 370 yards from Porcupine Creek.

While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Equipment - PRV vent lines do not comply with CECMC pressure safety device rules with a CA date of 05/13/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection/audit report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	ECD, thermogen & liquid nitrogen tank - hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tanks - hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 5		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Other	# 7		
Comment:	Chemical tanks, liquid nitrogen tank & thermogen not listed in operators FORM 2A or FORM 4 SUNDRY/not in compliance with CECMC rules		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	PRV vent lines do not comply with CECMC pressure safety device rules		
Corrective Action:	Comply with CECMC pressure safety device rules	Date:	05/13/2025
Type: Plunger Lift	# 17		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 17		
Comment:	Pressure transducers & Taylor plugs located on bradenheads, bradenhead valves are accessible		
Corrective Action:		Date:	
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 17		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 17		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Thermogen		

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:	Tank equipped with telemetry There are a total of three 300 bbl tanks in battery on location, 2 condensate & 1 produced water. FORM 2A document # 400130017 submitted by operator lists 2 condensate tanks & 0 water tanks/not in compliance with CECMC rules				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		
Comment:	Tanks equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Centralized containment			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	Ignitor/Combustor	
Comment:	SAVAGE RMV 15-35 well BH line connected to ECD - FORM 4 SUNDRY document #'s 403674396, 403901338 & 404137826 FORM 42 document # 403957085	
Corrective Action:		Date:

Inspected Facilities

Facility ID: 211129 Type: WELL API Number: 045-06888 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/13/2025 Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: 123 Fluid Type: GAS

End Surf Csg Pressure: 0

Comment: [BH line connected to ECD - FORM 4 SUNDRY document #'s 403674396, 403901338 & 404137826](#)

[FORM 42 document # 403957085](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 421918 Type: WELL API Number: 045-20449 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 421919 Type: WELL API Number: 045-20450 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 421920 Type: WELL API Number: 045-20451 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 421921 Type: WELL API Number: 045-20452 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 421922 Type: WELL API Number: 045-20453 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 421923 Type: WELL API Number: 045-20454 Status: SI Insp. Status: SI

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 421924 Type: WELL API Number: 045-20455 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 421925 Type: WELL API Number: 045-20456 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 421926 Type: WELL API Number: 045-20457 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 421927 Type: WELL API Number: 045-20458 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 421928 Type: WELL API Number: 045-20459 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 421929 Type: WELL API Number: 045-20460 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 421930 Type: WELL API Number: 045-20461 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 421931 Type: WELL API Number: 045-20462 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422119 Type: WELL API Number: 045-20492 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422187 Type: WELL API Number: 045-20520 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Gravel				Sparse to none
Sediment Traps						
				Material Handling And Spill Prevention		Chemical tank containments
		Ditches				
Gravel						Sparse to none in areas
Berms						
		Compaction				
Check Dams						
Compaction						Light compaction in some areas
		Culverts				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Equipment for corrective action & also refer to Equipment & Tanks & Berms for comments	smelserw	05/06/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708906423	Inspection/Audit 708906422 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7038027
708906424	Inspection/Audit 708906422 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7038028