

Inspection Photos

05/6/2025

Operator: GUNNISON ENERGY LLC - 10515

Location ID: 324484

Inspection Doc: 718100503

Gunnison County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324484



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location from south, southwest, northwest to north. Well on Location has been P&Ad, the tank battery and other production facilitates have been removed from the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324484



Photo 2: See comments under photo 2.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324484



Photo 3: Photos 3-4 taken from the west end of the Location. Photos provide an overview of the Location north, northeast, southeast to south. Well on Location has been P&Ad, the tank battery and other production facilities have been removed from the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324484



Photo 4: See comments under photo 3



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324484



Photo 5: Photo taken from the north end of the Location, facing east. Photo example showing the cut slopes on the Location. Slopes are bare and at risk of erosion and degradation due to runoff. Stormwater and erosion control BMPs are missing or insufficient at the cut slopes.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324484



Photo 6: Photos 6-7 taken from the cut slopes on the north end of the Location. Photos examples showing the slopes are bare and at risk of erosion and degradation due to runoff. Stormwater and erosion control BMPs missing or insufficient at the cut slopes.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324484



Photo 7: See comments under photo 6.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324484



Photo 8: Photos taken from the south end of the Location. Photos example showing the erosion log (straw wattle) has not been maintained in proper functioning condition, is in disrepair and is now considered debris.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324484



Photo 9: Photos 9-11 are examples showing fencing at excavations throughout the Location are in disrepair; fencing requires maintenance.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324484



Photo 10: See comments under photo 9 regarding fencing. Photos 10-11 also show pipe riser / surface equipment remaining on the Location. All surface equipment was required to be removed within 3 months after plugging and abandonment of the well.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324484



Photo 11: See comments under photo 10.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324484



Photo 12: Photo taken from the south end of the Location, facing south. Photo shows what appears to be a monitoring well. See comments under photo 10 regarding removal of surface equipment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources