

Final Reclamation Inspection

April 30, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 331225

Inspection Document #: 718800241

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-TEETS #15-20A
Location ID: 331225



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet final reclamation standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: HSR-TEETS #15-20A
Location ID: 331225



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: HSR-TEETS #15-20A
Location ID: 331225



Photo 5. Photo taken of the well location. Photo illustrates weedy growth, dominated by kochia (*Bassia scoparia*) and russian thistle (*Salsola tragus*).



Photo 6. Photo taken of the well location. Photo illustrates some bare soil piles were observed at the location.

Inspection Photos
Location Name: HSR-TEETS #15-20A
Location ID: 331225




Photo 7. Photo taken of the access road from the well location. the access road remains in place for another location, Location ID# 319288. Erosion was observed north of the access road (delineated with red arrow).



Photo 8. Photo taken of erosion north of the access road, directly east of the well site. A small gully, approximately one foot across and 8 feet in length has formed.

Inspection Photos
Location Name: HSR-TEETS #15-20A
Location ID: 331225



Photo 9. Photo taken of the reference area, north of the location, facing North. Photo illustrates perennial grass vegetation.