

Inspection Photos

Location Name: QB Energy BENZEL 36-2D (B36X) Pad

Location #: 335354



Photo # 9450 From Entrance to location




Photo # 9451 Location

Inspection Photos
Location Name: QB Energy BENZEL 36-2D (B36X) Pad
Location #: 335354



Photo # 9452 Location




Photo # 9453 Location

Inspection Photos
Location Name: QB Energy BENZEL 36-2D (B36X) Pad
Location #: 335354



Photo # 9454 Location



Photo # 9455 Location

Inspection Photos
Location Name: QB Energy BENZEL 36-2D (B36X) Pad
Location #: 335354



Photo # 9456 Location



Photo # 9457 Unmarked deadman

Inspection Photos
Location Name: QB Energy BENZEL 36-2D (B36X) Pad
Location #: 335354



Photo # 9458 Same unmarked deadman



Photo # 9459 Same unmarked deadman from a different angle

Inspection Photos
Location Name: QB Energy BENZEL 36-2D (B36X) Pad
Location #: 335354



Photo # 9460 Unmarked deadman



Photo # 9461 Same unmarked deadman

Inspection Photos
Location Name: QB Energy BENZEL 36-2D (B36X) Pad
Location #: 335354



Photo # 9462 Same unmarked deadman from a different angle



Photo # 9463 Unused flowline in secondary containment lacks lockout tagout (OOSLAT)

Inspection Photos
Location Name: QB Energy BENZEL 36-2D (B36X) Pad
Location #: 335354



Photo # 9464 Unused flowline near separators lacks lockout tagout (OOSLAT)



Photo # 9465 Unused flowline near separators lacks lockout tagout (OOSLAT)

Inspection Photos

Location Name: QB Energy BENZEL 36-2D (B36X) Pad

Location #: 335354



Photo # 9466 Unused flowline near separators lacks lockout tagout (OOSLAT)



Photo # 9467 Unused flowline near separators lacks lockout tagout (OOSLAT)

Inspection Photos

Location Name: QB Energy BENZEL 36-2D (B36X) Pad

Location #: 335354



Photo # 9468 Unused flowline near separators does not comply with CECMC lockout tagout (OOSLAT) rules

