

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/01/2025

Submitted Date:

05/08/2025

Document Number:

715202304

FIELD INSPECTION FORM

Loc ID 324891 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 81480
Name of Operator: THOMAS L SPRING LLC
Address: 7400 E ORCHARD RD STE 106-S
City: GREENWOOD State: CO Zip: 80111

Findings:

- 11 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Springs, Tom	303-771-1889	T1spring@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257925	WELL	SI	12/01/2022	GW	061-06765	LAKESIDE 1-21	SI

General Comment:

SE Compliance Specialist Brian Welsh conducted an audit and routine field inspection of the well location and equipment
Form 6A (403241957) was Approved on 11/29/22 with a plugging date of 12/31/27

Location

Lease Road:			
Type	Access		
comment:	Dirt road through pasture		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to fence at HGS		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stencils on water tank. Add NFPA label to tank		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Pipe fence around HGS and meter run		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe fence around wellhead		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	Meter run next to HHS		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	HHS on west side of wellhead		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		38.302710,-102.794460
Comment: Fiberglass open top water tank. Netting needs repaired. Tank has a minor leak on the west seam that needs repaired					
Corrective Action: Install or repair wildlife protection equipment					Date: <u>06/01/2025</u>
Paint					
Condition					
Other (Content)					
Other (Capacity)	210bbbls				
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Berms lack maintenance for capacity					
Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.					Date: <u>06/01/2025</u>
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 257925 Type: WELL API Number: 061-06765 Status: SI Insp. Status: SI

Producing Well

Comment: [Well is SI at time of inspection](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715202311	location photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7041663