

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC TWIN CREEK 12-6C1 (F12E) Pad

Location #: 421390



Photo # 25 From entrance to location



Photo # 26 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC TWIN CREEK 12-6C1 (F12E) Pad

Location #: 421390



Photo # 27 Location



Photo # 28 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC TWIN CREEK 12-6C1 (F12E) Pad

Location #: 421390



Photo # 29 Location



Photo # 30 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC TWIN CREEK 12-6C1 (F12E) Pad

Location #: 421390



Photo # 31 Location



Photo # 32 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC TWIN CREEK 12-6C1 (F12E) Pad

Location #: 421390



May 8, 2025 at 1:43:27 PM
CO

Photo # 33 Location



May 8, 2025 at 1:49:26 PM
CO

Photo # 34 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC TWIN CREEK 12-6C1 (F12E) Pad

Location #: 421390



Photo # 35 Location



Photo # 36 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC TWIN CREEK 12-6C1 (F12E) Pad

Location #: 421390



Photo # 37 Location



Photo # 38 Meter house is disconnected & not in use/unused equipment

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC TWIN CREEK 12-6C1 (F12E) Pad

Location #: 421390



Photo # 39 Staining inside secondary containment



Photo # 40 Staining inside secondary containment

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC TWIN CREEK 12-6C1 (F12E) Pad

Location #: 421390



Photo # 41 Staining inside secondary containment



Photo # 42 Staining near tank battery

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC TWIN CREEK 12-6C1 (F12E) Pad

Location #: 421390



Photo # 43 Staining near tank battery



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources