

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/09/2025

Submitted Date:

05/09/2025

Document Number:

716300944

FIELD INSPECTION FORM

Loc ID 322219 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 74975
Name of Operator: SAN MARCO PETROLEUM INC
Address: 240 MILWAUKEE ST STE 200
City: DENVER State: CO Zip: 80206-

Findings:

- 10 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|-----------------------|---------------------------------|
| Sheridan, John | 303-905-5919 | jsheridanvc@gmail.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 209942 | WELL | PR | 03/01/2021 | OW | 043-06020 | ADAMIC 1-20 | PR |

General Comment:

(This area is currently blank for general comments.)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | WEEDS | | |
| Comment: | PHOTO 5: WEEDS INSIDE TANK BATTERY BERMS. | | |
| Corrective Action: | REMOVE WEEDS INCLUDING ROOT STRUCTURES ON AND INSIDE TANK BATTERY BERMS PER RULE 606. | Date: | 05/21/2025 |
| Type | OTHER | | |
| Comment: | PHOTO 6: Mechanical issue well head leaking around tubing nut see video. | | |
| Corrective Action: | Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.. THIS IS THE SECOND NOTICE, IMMEDIATE ACTION IS REQUIRED. | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| Type | # | | corrective date |
|---------------------------|--|-------|-----------------|
| Type: Bradenhead | # 1 | | |
| Comment: | IS ACCESSABLE (BRADENHEAD IS LEAKING SEE HOUSEKEEPING FOR CORRECTIVE ACTION) | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | ELECTRIC DRIVE | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | ELECTRIC METER AND EQUIPMENT | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 2 | OTHER | STEEL AST | | 38.378851,-105.128139 |
| Comment: | TANKS HAVE NO PRESSURE RELIEF VALVE INSTALLED AND GAS IS LEAKING THROUGH GUAGE HATCH ON BOTH TANKS. SEE ATTACHED FLIRR VIDEO. | | | | |
| Corrective Action: | Tanks will function as sealed and ventless with gas released only through a vapor control system or properly sized pressure relief valve. per Rule 608.a.(9). | | | | Date: 05/12/2025 |

| | |
|------------------|----------|
| Paint | |
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | 210 BBL |
| Other (Type) | |

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Berms | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficent | Base Sufficent | Inadequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | | | |
|--------------------|----|--|-------|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|--|--|-------|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 209942 Type: WELL API Number: 043-06020 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/04/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: NOTE: BRADENHEAD IS LEAKING SO A PROPER BRADENHEAD TEST CANNOT BE PERFORMED. SEE HOUSEKEEPING FOR CORRECTIVE ACTION.

06/09/2025

Corrective Action: 7 DAYS AFTER REPAIRING BRADENHEAD LEAK PERFORM A PROPER BRADENHEAD TEST AND SUBMIT REPORT.

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|--|----------|------------|
| THIS IS A FOLLOW UP TO INSP. DOC #707901288, CA'S HAVE NOT BEEN ADDRESSED, IMMEDIATE ACTION IS REQUIRED. THIS IS A SECOND NOTICE ON BRADENHEAD LEAK. | beardslt | 05/09/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------|---|
| 716300945 | INSP. PHOTOS | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042575 |
| 716300946 | BRHD LEAK FLIRR VIDEO | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042577 |
| 716300947 | TANK BATTERY FLIRR VIDEO | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7042578 |