

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC BENZEL 25-10C (K25) Pad

Location #: 335344



Photo # 9636 From entrance to location



Photo # 9637 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC BENZEL 25-10C (K25) Pad

Location #: 335344



Photo # 9638 Location



Photo # 9639 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC BENZEL 25-10C (K25) Pad

Location #: 335344



Photo # 9640 Location



Photo # 9641 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC BENZEL 25-10C (K25) Pad

Location #: 335344




Photo # 9642 Unused flowlines lack lockout tagout (OOSLAT)



Photo # 9643 Unused flowline lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC BENZEL 25-10C (K25) Pad

Location #: 335344



Photo # 9644 Unused flowline lacks lockout tagout (OOSLAT)



Photo # 9645 Unused flowline lacks lockout tagout (OOSLAT)